

From:

Speedy Line Marking Au PTY LTD 16 Flack Avenue, Hillsdale NSW 2036 info@speedylinemarking.com.au ABN 32 673 397 503

Quote Number Quo-900 Quote Date September 12, 2024	Total	\$440.00
Quote Number QUO-900	Quote Date	
0110 000	Quote Number	QUO-900

To:

sales.alexandria@signarama.com.au sales.alexandria@signarama.com.au

Hrs/Qty	Service	Rate/Price	Sub Total
1	AREA ONE: Yellow striped no parking area 16m long A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$300.00	\$300.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Hrs/Qty	Service	Rate/Price	Sub Total
1	AREA TWO: Curved curb extends to 4.5m A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards ESTABLISHMENT FEES INCLUDED IN OVERALL PRICE: All work to be conducted in accordance with Australian standards Speedy Line Marking to provide all insurance documents if required Speedy Line Marking to provide SWNS if required Speedy Line Marking to provide Certificate of Currency if required Speedy Line Marking to provide Company Registration if required	\$100.00	\$100.00

Total	\$440.00
Tax	\$40.00
Sub Total	\$400.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.