



# Quote

**From:**

Speedy Line Marking Au PTY LTD

16 Flack Avenue, Hillsdale

NSW 2036

info@speedylinemarking.com.au

ABN 32 673 397 503

Quote Number	QUO-645
Quote Date	April 16, 2024
<b>Total</b>	<b>\$48,691.50</b>

**To:**

Build View

jay@buildview.net.au

Hrs/Qty	Service	Rate/Price	Sub Total
1	1 x disabled parking with 1 x shared zone A1 Dulux road master Antislip P5 aggregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$500.00	\$500.00
1	3 x staff parking bays with 3 x wheelstops and 3 x "staff" numbers 8,9,10 A1 Dulux road master Antislip P5 aggregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$600.00	\$600.00

Thanks for choosing [Speedy Line Marking | info@speedylinemarking.com.au](mailto:info@speedylinemarking.com.au)

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Hrs/Qty	Service	Rate/Price	Sub Total
1	6 x customer parking bays A1 Dulux road master Antislip P5 aggregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$180.00	\$180.00
1	1 x DROP OFF ZONE Writing 6.4m x 2.6 A1 Dulux road master Antislip P5 aggregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$400.00	\$400.00
1	5 x directional arrows A1 Dulux road master Antislip P5 aggregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$500.00	\$500.00
1	1 x ENTRY ONLY sign (500 x 350) to be installed at the Taren Point Road driveway Supply and install in accordance with rms Australian standard	\$550.00	\$550.00
1	1 x A NO ENTRY sign (500 x 350) and 1 x ALL TRAFFIC LEFT sign to be installed at the Parraween a Road exit driveway Supply and install in accordance with rms Australian standard	\$1,050.00	\$1,050.00
1	1 x The "LOADING BAY" to be signposted Supply and install in accordance with rms Australian standard	\$550.00	\$550.00

Thanks for choosing [Speedy Line Marking | info@speedylinemarking.com.au](mailto:info@speedylinemarking.com.au)

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Hrs/Qty	Service	Rate/Price	Sub Total
1	Aprrox 650m2 Epoxy Supply and install in accordance with rms Australian standard	\$32,500.00	\$32,500.00
1	1 x Metal Bike Rack Supply and install in accordance with rms Australian standard	\$800.00	\$800.00
1	9 x Yellow Powder coated Bollard Supply and install in accordance with rms Australian standard	\$4,500.00	\$4,500.00
1	1 x Pedestrian Crossing 15m x 2.6m approx with 15 bars A1 Dulux road master Antislip P5 agregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$1,335.00	\$1,335.00
1	2 x ONE WAY Writing A1 Dulux road master Antislip P5 agregate 2 years warranty all line marking to be applied in accordance with Australians standards	\$800.00	\$800.00

Sub Total	\$44,265.00
Tax	\$4,426.50
<b>Total</b>	<b>\$48,691.50</b>

Thanks for choosing [Speedy Line Marking | info@speedylinemarking.com.au](mailto:info@speedylinemarking.com.au)

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.