



Quote

From:

Speedy Line Marking Au PTY LTD
16 Flack Avenue, Hillsdale
NSW 2036
info@speedylinemarking.com.au
ABN 32 673 397 503

Quote Number	QUO-802
Quote Date	July 24, 2024
Total	\$1,496.00

To:

stephen.shaw@outlook.com
stephen.shaw@outlook.com

Hrs/Qty	Service	Rate/Price	Sub Total
22	Car bays with numbers (painted over existing line markings) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$40.00	\$880.00
4	Visitor Car bays (painted over existing line markings) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$40.00	\$160.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Hrs/Qty	Service	Rate/Price	Sub Total
1	Establishment fees All work to be conducted in accordance with Australian standards Speedy Line Marking to provide all insurance documents if required Speedy Line Marking to provide SWNS if required Speedy Line Marking to provide Certificate of Currency if required Speedy Line Marking to provide Company Registration if required	\$320.00	\$320.00

Sub Total	\$1,360.00
Tax	\$136.00
Total	\$1,496.00

Thanks for choosing [Speedy Line Marking | info@speedylinemarking.com.au](mailto:info@speedylinemarking.com.au)

Terms and Conditions: Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.