

From:	Quote Number	QUO-1319
Speedy Line Marking Au PTY LTD	Quote Date	May 6, 2025
16 Flack Avenue, Hillsdale	Total	\$24,480.50
NSW 2036		+ - · / · · · · · ·
info@speedylinemarking.com.au		
ABN 32 673 397 503		

To:

jasmine@nswdbm.com.au jasmine@nswdbm.com.au

Hrs/Qty	Service	Rate/Price	Sub Total
1	Bunnings Morriset: Hatching area to be refreshed (white) - approx 55m x 7m A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$3,000.00	\$3,000.00
2	Bunnings Morriset: Fire exit 'Keep Clear' A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$125.00	\$250.00
5	Bunnings Morriset: Directional arrows (repainted white) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$50.00	\$250.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. Please note the following points:



Hrs/Qty	Service	Rate/Price	Sub Total
3	Bunnings Morriset: Speed humps to be repainted A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$75.00	\$225.00
1	Bunnings Morriset: 'Restricted access' - outside door A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$125.00	\$125.00
1	Bunnings Morriset: Remove car bay line All grinding in accordance with Australian standard using diamond grinding tools	\$50.00	\$50.00
1	Bunnings Morriset: 'No Entry' - at gate A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$175.00	\$175.00
1	Bunnings Morriset: Watchout Forklift Shared Zone 'Text & Logo' (yellow) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$250.00	\$250.00
1	Bunnings Morriset: Directional arrow - faded to be redone (yellow) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$50.00	\$50.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. Please note the following points:



Hrs/Qty	Service	Rate/Price	Sub Total
100	Bunnings Morriset: approx 100 car bays to be refreshed A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$30.00	\$3,000.00
2	Bunnings Morriset: Disibility car bays A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$150.00	\$300.00
2	Bunnings Morriset: Shared zones A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$250.00	\$500.00
1	Bunnings Morriset: Truck Loading Zone (Back of the building) - lettering 0.300mm A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$800.00	\$800.00
1	OPTION: GRINDING - ALL GRINDING IN ACCORDANCE WITH AUSTRALIAN STANDARDS All grinding in accordance with Australian standard using diamond grinding tools	\$12,000.00	\$12,000.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. Please note the following points:



Hrs/Qty	Service	Rate/Price	Sub Total
1	Bunnings Morriset: Establishment Fee All work to be conducted in accordance with Australian standards Speedy Line Marking to provide all insurance documents if required Speedy Line Marking to provide SWNS if required Speedy Line Marking to provide Certificate of Currency if required Speedy Line Marking to provide Company Registration if required	\$1,280.00	\$1,280.00

Total \$24,480.50	Total
	Тах
Tax \$2,225.50	Sub Total

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. Please note the following points: