

From:

Speedy Line Marking Au PTY LTD 16 Flack Avenue, Hillsdale NSW 2036 info@speedylinemarking.com.au ABN 32 673 397 503

Total	\$1,776.50
Quote Date	April 8, 2025
Quote Number	QUO-1276

To: p.elmowy@rwre.com.au p.elmowy@rwre.com.au

Hrs/Qty	Service	Rate/Price	Sub Total
7	car bays with shop + number with black back ground 0.500mm (Letter and number 0.300mm) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$75.00	\$525.00
6	car bays with suite + number with black back ground 0.500mm Letter and number 0.300mm Al Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards	\$75.00	\$450.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Hrs/Qty	Service	Rate/Price	Sub Total
1	Establishment fees (after hours) All work to be conducted in accordance with Australian standards Speedy Line Marking to provide all insurance documents if required Speedy Line Marking to provide SWNS if required Speedy Line Marking to provide Certificate of Currency if required Speedy Line Marking to provide Company Registration if required	\$640.00	\$640.00

Total	\$1,776.50
Tax	\$161.50
Sub Total	\$1,615.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.