

## From:

Speedy Line Marking Au PTY LTD 16 Flack Avenue, Hillsdale NSW 2036 info@speedylinemarking.com.au ABN 32 673 397 503

| Total        | \$1,100.00        |
|--------------|-------------------|
| Quote Date   | February 26, 2025 |
| Quote Number | QUO-1182          |

## **To:** rossmanuel@bigpond.com rossmanuel@bigpond.com

| Hrs/Qty | Service  | Rate/Price | Sub Total  |
|---------|--|------------|------------|
| 1       | Pedestrian crossing - approx 10 (Establishment fees included) A1 Dulux road master 2 years warranty All line marking to be applied in accordance with Australians standards ESTABLISHMENT FEES INCLUDED IN OVERALL PRICE: All work to be conducted in accordance with Australian standards Speedy Line Marking to provide all insurance documents if required Speedy Line Marking to provide SWNS if required Speedy Line Marking to provide Certificate of Currency if required Speedy Line Marking to provide Company Registration if required | \$1,000.00 | \$1,000.00 |

| Sub Total | \$1,000.00 |
|-----------|------------|
|-----------|------------|

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



| Total | \$1,100.00 |
|-------|------------|
| Tax   | \$100.00   |

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.