

From:

Speedy Line Marking Au PTY LTD 16 Flack Avenue, Hillsdale NSW 2036 info@speedylinemarking.com.au ABN 32 673 397 503

Total	\$2,838.00
Quote Date	July 9, 2024
Quote Number	QUO-766

To:WSPServices Kurt@WSPServices.com.au

Hrs/Qty	Service	Rate/Price	Sub Total
2	Paint 2 thirds of the parking bay blue with non-slip additive A1 Dulux road master Antislip P5 agregatee 2 years warranty All line marking to be applied in accordance with Australians standards	\$700.00	\$1,400.00
2	stencil in white (Stencil supplied by WSP) – 1 per bay A1 Dulux road master Antislip P5 agregatee 2 years warranty All line marking to be applied in accordance with Australians standards	\$150.00	\$300.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Hrs/Qty	Service	Rate/Price	Sub Total
1	Estimate 8m of kerbing to be painted safety yellow with non-slip additive. A1 Dulux road master Antislip P5 agregatee 2 years warranty All line marking to be applied in accordance with Australians standards	\$240.00	\$240.00
1	Establishment fees Supply and install in accordance with Australian standard All work in accordance with Australian standard	\$640.00	\$640.00

Total	\$2,838.00
Tax	\$258.00
Sub Total	\$2,580.00

Thanks for choosing Speedy Line Marking | info@speedylinemarking.com.au

Terms and Conditions: Line marking to designated area as per specifications. **Please note**the following points:

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.