



# Quote

**From:**

Speedy Line Marking Au PTY LTD  
 16 Flack Avenue, Hillsdale  
 NSW 2036  
 info@speedylinemarking.com.au  
 ABN 32 673 397 503

Quote Number	QUO-837
Quote Date	August 13, 2024
<b>Total</b>	<b>\$11,704.00</b>

**To:**

david.axisa@global.komatsu  
 david.axisa@global.komatsu

Hrs/Qty	Service	Rate/Price	Sub Total
1	<b>WAREHOUSE: Shot Blasting</b> Shot blasting: removal of debris, irregularities and other contaminants from concrete, metal, and other industrial surfaces. All work in accordance with Australian standard 5 YEAR WARRANTY	\$10,000.00	\$10,000.00
1	<b>Establishment fees</b> 3x days on site All work to be conducted in accordance with Australian standards Speedy Line Marking to provide all insurance documents if required Speedy Line Marking to provide SWNS if required Speedy Line Marking to provide Certificate of Currency if required Speedy Line Marking to provide Company Registration if required	\$640.00	\$640.00

Thanks for choosing [Speedy Line Marking | info@speedylinemarking.com.au](http://Speedy Line Marking | info@speedylinemarking.com.au)

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.



Sub Total	\$10,640.00
Tax	\$1,064.00
<b>Total</b>	<b>\$11,704.00</b>

---

Thanks for choosing [Speedy Line Marking | info@speedylinemarking.com.au](mailto:info@speedylinemarking.com.au)

**Terms and Conditions:** Line marking to designated area as per specifications. **Please note the following points:**

Line marking is weather dependant, Area should not be driven over for a certain period, please refer to product specification for full details, Vehicles to be removed prior to attending site to complete works, Area to be clear of any obstacles which may impede line marking.